

SMWD INSPECTION
RECORD DRAWINGS

DATE _____

SIGNATURE _____

INSPECTOR

Inspector Stamp and "Record Drawing" Placement Instructions

1)

SMWD INSPECTION RECORD DRAWINGS
DATE <u>7-22-02</u>
SIGNATURE <u>Tou Jue</u> INSPECTOR

Add SMWD Inspector Stamp to cover sheet of Record Drawings

2)

2	5/01/02	JLB	RECORD DRAWING	<i>JEA</i>	7-23-02	JOB NO. S30-116-01	DESIGN J. BOY
1	9/20/01	JLB	NOTATION OF REVISED PLAN SHEETS	<i>JEA</i>	9/24/01	DRAWING NO. D-518	CHECK T. HOO
REV.	DATE	BY	DESCRIPTION	APPROVED	DATE		

Add dated "Record Drawing" line to revision block (on all sheets)